

Letter to J. W. Willoway

June 9 57

1. Same objection as before to decoration of ~~the~~
~~the~~ tympanum
2. windows & portico (in drawing unequal
in size irregular in position, ought not
to have shelf & cornice.
3. Dome would be better if more elliptical
Dome too heavy -
4. suggestion whether chimney could
not be hidden by ^{at end} piercing in rear wall
5. termination of roof of wings bad.
elevation over raising cornice bad ef-
fect. suggest continuity crown molding
along eaves - sides allowing (this to)
rise above roof or making roof and
pediment flatter -

General defect wings too light, dome too
heavy. Drawing shows too heavy
shadow of portico & wing —
complaint of darkness of rooms — rear —
suggestions how to cure it —

P. S. suggesting reducing height of dome by
about $\frac{1}{4}$ bringing base of cornice down be-
tween panel & windows